DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015890 Address: 333 Burma Road **Date Inspected:** 22-Jul-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes NA No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG components.

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

ZPMC SHIP – 19: OBG Seg 8AW, Seg 8BW and Seg 8CW.

This QA Inspector along with Mr. Manikandan Murugan photographed and documented various locations of OBG Seg 8AW, Seg 8BW and Seg 8CW; prior to the shipment of Voyage 4 (en-route to Yerba Buena Island, California, USA). Photographs were taken and documented for the locations and are available for review upon request.

Details are as follows:

- OBG Seg 8AW Panel Point (PP) 61 to PP64.
- OBG Seg 8BW PP65 to PP67.
- OBG Seg 8CW PP68 to PP71.

Photographs were taken and documented in the following sequence (starting from OBG Seg 8AW PP61 to Seg 8CW PP71):

1) Corner Assembly – Bike Path side.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

- 2) Longitudinal Diaphragm Bike Path side.
- 3) Chevron diagonal members (upper and lower) Bike Path side.
- 4) Sea fasteners.
- 5) Chevron diagonal members (upper and lower) Cross Beam side.
- 6) Longitudinal Diaphragm Cross Beam side.
- 7) Corner assembly Cross Beam side.
- 8) Truss post Cross Beam side.

The photographs and its sequence details are documented and are submitted to the Task Leader for review.

Trial Assembly:

Notification no: 006254.

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector has generated MT report for this date. The member(s) are identified as OBG components – Seg 9CE and Seg 9DE. The weld designations reviewed are as follows:

- 1) SP690-001 023 and 024.
- 2) SP545-001 035 and 036.
- 3) SP585-001 027, 028, 031 and 032.
- 4) BP180-001 053 and 054.
- 5) BP072-001 045 and 046.
- 6) EP146A-001 009 and 010.
- 7) DP698-001 015 and 016.
- 8) SP546A-001 042 and 043.
- 9) BP181-001 041 and 042.
- 10) BP073-001 033 and 034.
- 11) EP147A-001 009 and 010.
- 12) DP699A-001 009 and 010.
- 13) SP586-001 020, 021, 024 and 025.
- 14) SP691-001 023 and 024.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT (Continued Page 3 of 3)

Inspected By:	Wadkar, Sailesh	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer